

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
1	6504		Phinney Ave N	low tree pit								
2	6508 1/2		Phinney Ave N	low tree pit and weeds. Pilchuck (or other co.) to enlarge pit	x	x						
3	6510 1/2		Phinney Ave N	possible plantings/keep pit small								
4	6512		Phinney Ave N	unidentified maple, possible plantings								
5	6514		Phinney Ave N	Hedge Maple, needs pruning, low branches, remove concrete tiles and red lava rocks, remove timber frames, low water utility box					x		x	
6	6518		Phinney Ave N	Hedge Maple, needs pruning, tree pit size okay, weeds		x					x	
7	6518		Phinney Ave N	Hedge Maple, needs pruning, tree pit size okay, weeds		x					x	
8	6528		Phinney Ave N	Invasive Ivy on tree, magnolia tree, lots of grass, need pruning			x				x	between 6528 & 6532
9	6532		Phinney Ave N	Invasive Ivy on tree, magnolia tree, lots of grass, need pruning			x				x	between 6528 & 6533
10		6506	Phinney Ave N	Large Elm- okay, in front of PNC								
11	6532		Phinney Ave N	Hedge Maples: two tree pits								
12	6532		Phinney Ave N	Birch tree- beginning of re-done planting strip								north of 6532
13		6509	Phinney Ave N	in planting strip- nice								across from pole
14	6710		Greenwood Ave N	Mtn. Ash- invasive, needs to be removed- next to light pole			x					south of 6710
15	6722		Greenwood Ave N	Green Beech tree, needs pruning weeds, old plantings, timbers around pit		x					x	
16		6704B	Greenwood Ave N	Green Beech tree, weeds, old plantings, timbers around pit		x						north of pole
17	6732		Greenwood Ave N	No tree, weeds,		x						
18	6800		Greenwood Ave N	Dead tree/weeds, was hornbeam		x				x		
19	6800		Greenwood Ave N	Hornbeam tree, weeds, grass integrated into roots system, cost would be about \$200 to clean up		x						
20	6814		Greenwood Ave N	Tree Missing, possible Hornbeam						x		
21	6814		Greenwood Ave N									north of 6814

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
22	6820		Greenwood Ave N	3 Tree Pits, some plantings, Hornbeams								
23	6820		Greenwood Ave N	3 Tree Pits, some plantings, Hornbeams								
24	6820		Greenwood Ave N	3 Tree Pits, some plantings, Hornbeams								
25		7002	Greenwood Ave N	next to bus stop, hornbeam- needs mulch, weeding		x						next to pole
26		7002	Greenwood Ave N	next to bus stop, hornbeam- needs mulch, weeding		x						next to pole
27		7002	Greenwood Ave N	Red Bud, needs pruning, split, candidate for replacement, will not thrive							x	next to pole
28		7002	Greenwood Ave N	Tree Missing, weeds		x				x		next to pole
29	7100		Greenwood Ave N	Crab Apple, has a fabric weed barrier and gurdle around tree, should be removed					x			
30	7104		Greenwood Ave N	Crab Apple, has a fabric weed barrier and gurdle around tree, should be removed					x			
31		7102	Greenwood Ave N	Tree was topped								
32	7114-7120		Greenwood Ave N	Mountain Ash, potential for stepping stones, plantings, check if irrigation still works								
33	7114-7120		Greenwood Ave N	Mountain Ash, potential for stepping stones, plantings, check if irrigation still works								
34	7114-7120		Greenwood Ave N	Mountain Ash, potential for stepping stones, plantings, check if irrigation still works								
35	7314		Greenwood Ave N	Vine must be removed, some plantings Green Beech			x					
36	7314		Greenwood Ave N	Vine must be removed, some plantings Green Beech			x					
37	3718		Greenwood Ave N	Tree missing, lots of weeds		x				x		
38	7400		Greenwood Ave N	Needs pruning, possibly add pavers next to curb							x	
39	7400		Greenwood Ave N	Needs pruning, possibly add pavers next to curb							x	
40	7400		Greenwood Ave N	Needs pruning, possibly add pavers next to curb							x	
41	7406A		Greenwood Ave N	weeds, needs pruning		x						
42	7419		Greenwood Ave N	weeds		x						
43			Greenwood Ave N	nice block, new tree pits, could add plantings, sidewalk width only 4 ft.								
44			Greenwood Ave N	Raised trees, sidewalk okay								Between 76th & N 77th
45	7610-7614		Greenwood Ave N	Grass, trip hazard								
46	7610-7614		Greenwood Ave N	Grass, trip hazard								

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
47	7618-7620		Greenwood Ave N	again grass- encourage keep grass but maintain								
48	7618-7620		Greenwood Ave N	again grass- encourage keep grass but maintain								
49	7618-7620		Greenwood Ave N	again grass- encourage keep grass but maintain								
50	7700		Greenwood Ave N	pavers upheaved, can enlarge pit 12 ft. almost	x			x				
51	7704		Greenwood Ave N	pavers upheaved, can enlarge pit 12 ft. almost	x			x				
52	7704		Greenwood Ave N	not a problem of trips								
53			Greenwood Ave N	enlarge tree pit	x							
53	7711		Greenwood Ave N	brought in soil								across from 7711
54	7711		Greenwood Ave N	brought in soil								across from 7711
56		7802	Greenwood Ave N	pavers upheaved, can enlarge pit	x			x				
57		7802	Greenwood Ave N	pavers upheaved, can enlarge pit	x			x				
58	7814		Greenwood Ave N	not much to do								
59	7814		Greenwood Ave N	not much to do								
60	7814		Greenwood Ave N	not much to do								
61	7900		Greenwood Ave N	not much tree pit, could enlarge	x							
62	7912		Greenwood Ave N	enlarged tree pit with plantings	x							
63			Greenwood Ave N	small tree pit	x							
64			Greenwood Ave N									
65			Greenwood Ave N	Tree on private property needs trimming- overhangs low over sidewalk								
66	7915		Greenwood Ave N									in front of
67			Greenwood Ave N	weeds		x						
68	7901		Greenwood Ave N	hole- on sidewalk								
69	7907		Greenwood Ave N	tree needs pruning							x	
70	7903		Greenwood Ave N									
71	7903		Greenwood Ave N									
72	7801		Greenwood Ave N	2 tree pits, pavers upheaved				x				
73	7801		Greenwood Ave N	2 tree pits, pavers upheaved				x				
74			Greenwood Ave N	not as bad- same block as 72, 73, remove pavers								corner of N 78th
75	7719		Greenwood Ave N	Pavers should be removed				x				
76	7717		Greenwood Ave N	Pavers should be removed				x				

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
77	7707		Greenwood Ave N	Close to driveway								
78	7707		Greenwood Ave N	Close to driveway								
79	7619		Greenwood Ave N	weeds		x						
80	7613		Greenwood Ave N	Pavers should be removed				x				
81	7613		Greenwood Ave N	Curb Broken, Trip Hazard								
82	7601		Greenwood Ave N	Mostly asphalt- but difficult to get a clear or smooth cut, may leave along					x			
83	7515-7521		Greenwood Ave N	No trip hazards, grass okay								
84	7515-7521		Greenwood Ave N	No trip hazards, grass okay								
85	7513		Greenwood Ave N	Pavers should be removed				x				
86			Greenwood Ave N	Grass/add plantings								
87	7501		Greenwood Ave N	Remove concrete, enlargen tree pit	x							
88	7501		Greenwood Ave N	Remove asphalt, enlargen tree pit	x							
89	7423		Greenwood Ave N	Box removal					x			
90	7419		Greenwood Ave N	Box removal					x			
91	7407		Greenwood Ave N	Box removal, plantings					x			
92	7403		Greenwood Ave N	Remove rocks, add plantings					x			
93	7321		Greenwood Ave N	Box should be removed					x			
94	7317		Greenwood Ave N	ivy around tree should be removed			x					
95	7311		Greenwood Ave N									
96	7303		Greenwood Ave N	weed barrier, ivy			x		x			Corner of N. 73rd
97			Greenwood Ave N	weed barrier removal					x			
98	7209		Greenwood Ave N									
99	7209		Greenwood Ave N									
100	7209		Greenwood Ave N									
101	7109		Greenwood Ave N	weed barrier removal					x			
102	7107		Greenwood Ave N									
103	7023		Greenwood Ave N									
104	7013		Greenwood Ave N	private residence								
105	7009		Greenwood Ave N	needs plantings								
106	7009		Greenwood Ave N	needs plantings								
107	7009		Greenwood Ave N	tree missing, trip hazard						x		
108	6817		Greenwood Ave N									
109	6815		Greenwood Ave N	Ivy, weed barrier			x					
110	6729		Greenwood Ave N	weeds, two pits		x						

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
111	6729		Greenwood Ave N	weeds, two pits		x						
112	6725		Greenwood Ave N									
113	6715-6717		Greenwood Ave N									
114	6715-6717		Greenwood Ave N									
115			Phinney Ave N	on planting strip/property- tree needs pruning							x	
116	6517		Phinney Ave N	rocks should be removed					x			
117	6511		Phinney Ave N	tree pit enlarged, plantings								
118	6509		Phinney Ave N	weeds, need plantings		x						
119	6505		Phinney Ave N	weeds, need plantings		x						
120	8515		Greenwood Ave N	enlarged pit	x							in front of
121	8523		Greenwood Ave N									
122	8533		Greenwood Ave N	2 tree pits, tree grate not level, some sidewalk ramping								next to
123	8533		Greenwood Ave N	sidewalk uprooted								
124	8533		Greenwood Ave N	sidewalk uprooted								
125	8533		Greenwood Ave N	sidewalk uprooted								
126	8539		Greenwood Ave N	pavers upheaving, plantings need pruning				x				
127	8543		Greenwood Ave N	tree missing, asphalt						x		
128	8549		Greenwood Ave N	one side of sidewalk new, other old								
129			Greenwood Ave N	new pits								
130			Greenwood Ave N	new pits								
131			Greenwood Ave N	new pits								
132			Greenwood Ave N	new pits								
133	8701		Greenwood Ave N	7 pits w/ ivy and bark		x						
134	8701		Greenwood Ave N	7 pits w/ ivy and bark		x						
135	8701		Greenwood Ave N	7 pits w/ ivy and bark		x						
136	8701		Greenwood Ave N	7 pits w/ ivy and bark		x						
137	8701		Greenwood Ave N	7 pits w/ ivy and bark		x						
138	8701		Greenwood Ave N	7 pits w/ ivy and bark		x						
139	8701		Greenwood Ave N	7 pits w/ ivy and bark		x						
140	8733		Greenwood Ave N	grass, root upheaval, trip hazard								
141	8735		Greenwood Ave N	grass, root upheaval, trip hazard, shoots								between
142	8735		Greenwood Ave N	grass, root upheaval, trip hazard, shoots								between
143	8737		Greenwood Ave N	grass, root upheaval, trip hazard, shoots								between
144	8745		Greenwood Ave N	concrete barrier								
145	8745		Greenwood Ave N	concrete barrier								

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
146	8745		Greenwood Ave N	concrete barrier, dying tree					x			
147	8745		Greenwood Ave N	concrete barrier, dying tree					x			
148	8745		Greenwood Ave N	concrete barrier								
149	8745		Greenwood Ave N	concrete barrier, rootball showing					x			
150	8760		Greenwood Ave N	4 pits, some ivy		x						
151	8760		Greenwood Ave N	4 pits, some ivy		x						
152	8760		Greenwood Ave N	4 pits, some ivy		x						
153	8760		Greenwood Ave N	4 pits, some ivy		x						
154	8750		Greenwood Ave N	2 pits, some ivy			x					
155	8750		Greenwood Ave N	2 pits, some ivy			x					
156	8704		Greenwood Ave N	plantings, large pits								north of
157	8704		Greenwood Ave N	plantings, large pits								north of
158	8704		Greenwood Ave N	planting strip, 2 trees, one old one new								
159	8704		Greenwood Ave N	planting strip, 2 trees, one old one new								
160	8704		Greenwood Ave N	planting strip, 2 trees, one old one new								
161	8704		Greenwood Ave N	5 pits								
162	8704		Greenwood Ave N	5 pits								
163	8704		Greenwood Ave N	5 pits								
164	8704		Greenwood Ave N	5 pits								
165	8704		Greenwood Ave N	5 pits								
166	8580		Greenwood Ave N	need to enlarge pit, soil amendment	x							
167	8580		Greenwood Ave N	need to enlarge pit, soil amendment	x							
168	8574		Greenwood Ave N									
169	8574		Greenwood Ave N	pit needs to be cut	x							
170	8564		Greenwood Ave N	needs cut to sidewalk	x							
171	8560		Greenwood Ave N	enlarge	x							
172	8560		Greenwood Ave N	enlarge	x							
173	8556		Greenwood Ave N	enlarge	x							
174	8552 1/2		Greenwood Ave N	tree missing, asphalt						x		
175	8550		Greenwood Ave N	tree missing, asphalt						x		
176	8544		Greenwood Ave N	enlarge	x							
177	8536		Greenwood Ave N	enlarge, utility in way	x							
178	8530		Greenwood Ave N	enlarge	x							between
179	8524		Greenwood Ave N	enlarge	x							
180	8516		Greenwood Ave N	tree dead, stump- EIF grant to replace tree						x		
181		8502	Greenwood Ave N	remove grate					x			corner

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
182			N. 85th Street	enlarge, remove pavers	x			x				
183			N. 85th Street	enlarge, remove pavers	x			x				
184			N. 85th Street	enlarge, remove pavers	x			x				
185			N. 85th Street	enlarge	x							
186			N. 85th Street	remove pavers				x				
187			N. 85th Street	tree missing						x		
188		402	N. 85th Street	3 pits								
189		402	N. 85th Street	3 pits								
190		402	N. 85th Street	3 pits								
191		402	N. 85th Street	3 pits								
192	424		N. 85th Street									
193	424		N. 85th Street									
194	424		N. 85th Street	tree missing, SDOT sign						x		
195	424		N. 85th Street	tree missing, SDOT sign						x		
196	514		N. 85th Street	planting strip, 5 trees								
197	514		N. 85th Street	planting strip, 5 trees								
198	600		N. 85th Street	planting strip, 5 trees								
199	620		N. 85th Street	2 trees								
200	620		N. 85th Street	2 trees								
201	8420		Dayton Ave. N	2 trees								
202	8420		Dayton Ave. N	2 trees								
203		309	N. 85th Street	enlarge	x							
204		309	N. 85th Street	enlarge	x							
205	415		N. 85th Street	enlarge	x							
206	415		N. 85th Street	enlarge	x							
207	415		N. 85th Street	enlarge	x							
208	415		N. 85th Street	enlarge	x							
209		307	N. 85th Street	clean up,enlarge	x							
210		307	N. 85th Street	clean up,enlarge	x							
211	323		N. 85th Street	2 trees, enlarge	x							
212	323		N. 85th Street	2 trees, enlarge	x							
213	315		N. 85th Street	2 pits, enlarge	x							
214	315		N. 85th Street	2 pits, enlarge	x							

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
215		303	N. 85th Street	needs opening, but gas main, remove utilities	x							in front of
216	8420		Greenwood Ave N	enlarge tree pit	x							
217	8420		Greenwood Ave N	enlarge tree pit	x							
218	8414		Greenwood Ave N	pushing curb out								
219		8404	Greenwood Ave N	stump						x		
220	8408		Greenwood Ave N	enlarge tree pit	x							between
221	8404		Greenwood Ave N	enlarge tree pit	x							between
222	8402		Greenwood Ave N	overgrown tree							x	
223	8218		Greenwood Ave N	pavers uprooted, tree health?				x				
224	8214		Greenwood Ave N	enlarge, but utility pole	x							
225	8202		Greenwood Ave N	planting strip, trip hazard, utility pole								
226			Greenwood Ave N	planting strip, trip hazard, utility pole								
227	8102		Greenwood Ave N	enlarge tree pit	x							
228	8102		Greenwood Ave N	enlarge tree pit	x							
229	8008		Greenwood Ave N	no pit, ok healthy trees								
230	8008		Greenwood Ave N	no pit, ok healthy trees								
231	8004		Greenwood Ave N	pavers uprooted, enlarge	x			x				
232	8003		Greenwood Ave N	ivy up tree, enlarge	x		x					
233	8005		Greenwood Ave N	ivy, mound			x					
234	8009-8015		Greenwood Ave N	enlarge tree pit	x							
235	8009-8015		Greenwood Ave N	enlarge tree pit	x							
236	8009-8015		Greenwood Ave N	enlarge tree pit	x							
237	8103		Greenwood Ave N	cut								
238	8105		Greenwood Ave N	no needs								
239	8113-8119		Greenwood Ave N	enlarge tree pit	x							
240	8113-8119		Greenwood Ave N	enlarge tree pit	x							
241	8113-8119		Greenwood Ave N	enlarge tree pit	x							
242	8201		Greenwood Ave N	pruning							x	
243	8205		Greenwood Ave N	pruning							x	
244	8213		Greenwood Ave N	enlarge	x							
245	8215		Greenwood Ave N	3 trees in planting strip								
246	8215		Greenwood Ave N	3 trees in planting strip								
247	8221		Greenwood Ave N	3 trees in planting strip								
248	8317		Greenwood Ave N	open up	x							
249	8403		Greenwood Ave N	enlarge	x							
250	8409		Greenwood Ave N	enlarge	x							

Tree Pit Survey: Greenwood/Phinney Ridge

Photo	Address Building	Address Pole	Street	Comments	enlarge pits	weed	invasive	pavers upheaved or remove	Remove Other	Tree Missing	Pruning needed	directional details
251	8411		Greenwood Ave N	enlarge	x							
252	8421		Greenwood Ave N	enlarge tree pit	x							
253	8421		Greenwood Ave N	enlarge tree pit	x							
254			N. 85th Street	enlarge	x							
255	213		N. 85th Street	open up	x							
256	213		N. 85th Street	open up	x							
257	213		N. 85th Street	open up	x							
258	201		N. 85th Street	open up	x							
259	129		N. 85th Street	tree missing						x		
260	123		N. 85th Street	small tree pit	x							
261	123		N. 85th Street	small tree pit	x							
262	119		N. 85th Street	enlarge tree pit	x							
263	119		N. 85th Street	enlarge tree pit	x							
264	101		N. 85th Street	enlarge	x							
265			N. 85th Street	enlarge tree pit	x							
266	200		N. 85th Street									

Business	tree
Phinney Neighborhood Center	
Phinney Neighborhood Center	
Phinney Neighborhood Center	elm
Phinney Neighborhood Center	maple
Phinney Neighborhood Center	birch
Phinney Neighborhood Center	
Near Red Mill Burger	mtn. ash
Stumbling Goat	beech
Stumbling Goat	beech
Kort Haus Bar	
Old gas station	hornbeam
Old gas station	hornbeam

Business	tree
Johnson and Johnson Antiques	hornbeam
Johnson and Johnson Antiques	hornbeam
Johnson and Johnson Antiques	hornbeam
A-1 Piano	hornbeam
A-1 Piano	hornbeam
A-1 Piano	red bud
A-1 Piano	
Greentree Apartments	crab apple
Greentree Apartments	crab apple
Greentree Apartments	
Bakker's Dry Cleaning: 3 trees in front of condos	
Bakker's Dry Cleaning: 3 trees in front of condos	
Bakker's Dry Cleaning: 3 trees in front of condos	
Carmelitas	
Carmelitas	
Between Embellishment and Herkimer's Coffee	
Rising Star	
Rising Star	
Rising Star	
Auto Technician	
Lutheran Church	
In front of apt. building	
In front of apt. building	
In front of apt. building	

Business	tree
In front of apt. building	
In front of apt. building	
In front of apt. building	
in front of abandoned building	
new building, not occupied on ground floor	
new building, not occupied on ground floor	
Woodland Park United Methodist Church	
Woodland Park United Methodist Church	
Matt's Auto Care	
Hair style business	
Diva Espresso	
across from Diva Espresso	
Private residence, across from Diva	
Private residence	
Private residence	
Private residence	
Private residence	
modern dog business	
modern dog business	
The Sandra Apts.	
The Sandra Apts.	
The Sandra Apts.	

Business	tree
John Walkers Workshop	
John Walkers Workshop	
Pelayo Antiques	
Chinese Restaurant	
private residence	
Orowheat, Bakery Outlet	
Orowheat, Bakery Outlet	
Orowheat, Bakery Outlet	
Phinney Ridge Professional Center	
Pretty Parlour	

Business	tree
Pretty Parlour	
Espresso Dental	
Private residence	
Private residence	
Private Apts.	
Private residence	
Private residence	
Private residence	
Shenman Healing Center	
Greenwood Neighborhood Service Center	maple
Romeo's Pizza	maple
McDonald's	
Gary's Games	maple
Rosie's Room	
The Towers on Greenwood	
The Towers on Greenwood	
The Towers on Greenwood	
The Towers on Greenwood	
Walgreen's	maple
Walgreen's	maple
Walgreen's	maple
Walgreen's	maple
Walgreen's	maple
Walgreen's	maple
Walgreen's	maple
OK Corral	maple
apartments & OK Corral	maple
apartments & OK Corral	maple
apartments & OK Corral	maple

Business	tree
Westview North	maple
Westview North	maple
Westview North	maple
Westview North	maple
Westview South	maple
Westview South	maple
Safeway	
Safeway	
Safeway	
Safeway	
Safeway	
Safeway	
Safeway	
Safeway	
Safeway	
Safeway	
Safeway	
Safeway	
China Jade	
China Jade	
metal building	
metal building	
Neilson's	
vacant building	
vacant building	
DeGrazia's Hair Salon	
Buster's Brown Bag	
Sol Floris	
Greenwood Books	
Thai Food & La Conasupo Market	
Fredrick's Salon	
vancant building	
Washington Mutual	

Business	tree
Washington Mutual	
Washington Mutual	
Washington Mutual	
DMV, across street from Joslin Upholster	maple
DMV, across street from Joslin Upholster	maple
DMV, across street from Joslin Upholster	maple
Bank of America	
Bank of America	
Bank of America	
Bank of America	
vacant building	
vacant building	
vacant building	
vacant building	
new building	
new building	
Evanston Square Professional Suites	
Denise Hunt Townhouses	
Denise Hunt Townhouses	
vacant building	
vacant building	
Encore Media Group	
Encore Media Group	
Greenwood Medical Clinic	
Greenwood Medical Clinic	
Greenwood Medical Clinic	
Greenwood Medical Clinic	
parking lot	
parking lot	
Medicine Man	
Medicine Man	
Joslin Upholstery	
Joslin Upholstery	

Business	tree
bus stop	
The Upper Crust	
The Upper Crust	
vacant building	
Pig 'n' Whistle	
Steven Cole Salon	
Cobblestone Furniture	
Rosewood Guitar	
	aspen
Antique Lighting Co.	
Arita Japanese Restaurant	
Arita Japanese Restaurant	
Greenwood Quick Stop	
Greenwood Quick Stop	
Taco del Mar	
P.R. Cabinet Co.	
Seattle Martial Arts	
Second Skin	
private residence	
private residence	
commercial business	
commercial business	
Linda Fukuda Dental	
private residence	
PR Animal Hospital	
Trademark Graphic Services	
private residence	
private residence	
Mud Bay	
All American Realty	
Laughlin Gallery	
Hair Co.	

Business	tree
Mr. Gyro	
Antiko	
Gorditos	
Gorditos	
parking lot	
Kumon	
Emerald City Plaque	
Emerald City Plaque	
Squirrel's Second Hand	
Squirrel's Second Hand	
Blockbuster Video & Bartell's	
Kate's	